EXHIBIT 23

CASE 0:15-md-02666-JNE-DTS Doc. 941 Filed 10/03/17 Page 2 of 2

Subject: Scott, Mark 7/28/2006 FW: Bair Hugger Customer Query/Compaint

Priority: High

Status: Completed Percent Complete: 100%

Date Completed: Sunday, November 12, 2006

Total Work: 0 minutes Actual Work: 0 minutes

Owner: Unknown

Categories: @Waiting For

Hi Mark, Any thoughts on this question? Regards, Bob Bob Buehler +44 1924 887 401 - office

+44 7971 386 704 - mobile

From: Robert Press [mailto:Robert@intermed.co.nz]

Sent: Friday, July 14, 2006 2:24 AM

To: Buehler, Bob

Cc: Van Duren, Al; Janet Jordaan; Sarah Hare Subject: Bair Hugger Customer Query/Compaint

Importance: High

Hi Bob,

I have received a customer query/complaint regarding our Bair Huggers. Ironically this is the same individual we are also dealing with in relation to the Ranger 245.

The concern is that they have found air entering the blowing system that is bypassing the filter.

During a repair they removed the top assembly of the Bair Hugger and saw a collection of dust particles at each of the down facing holes at the rear of the assembly as well as dust over the circuit board. They feel this could be the result of the rotation of the centrifuge of the blower effectively sucking the air up through the holes, over the circuit board and then into the system. They are concerned that this may result in contaminated air particles bypassing the filtration system and making contact with the

patient.

Other units in their stock have also been checked and found to show the same result.

Lies Constant their stock have also been encoked and round to show the

I look forward to your comments.

Regards Robert Robert Press Field Sales Manager InterMed Medical Ltd www.intermed.co.nz Mobile: 021 760189

Email: robert.press@intermed.co.nz